



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
SUPERFUND SITE STRATEGY RECOMMENDATION - REGION 06

Site Name: Standard Brake Shoe and Foundry CERCLIS ID#: ARN0006066789

Alias Site Names: _____

Address: 3200 Pullen Street

City/County or Parish/State/Zip Code: Pine Bluff, Jefferson County, Arkansas

Report Type, Date, and Author: Site Inspection Sampling Work plan, April, 2008 ADEQ

RECOMMENDATION

☐ 1. No Further Remedial Action Planned
under Superfund (NFRAP)

☒ 2. Further Investigation Needed Under Superfund

☐ PA ☐ HRS Priority: ☐ High
☒ SSI ☐ RA ☐ Medium
☐ ESI ☐ RI/FS ☒ Low
☐ Other: Implement proposed SI work plan activities.
To be performed by: ADEQ

☐ 3. Action Deferred to:
☐ RCRA ☐ NRC

NOTIFY AUTHORITY:

☐ Removal ☐ RCRA ☐ TSCA ☐ CAA ☐ SMCRA
☐ Remedial ☐ State ☐ NPDES ☐ NRC ☐ Resource Trustee: _____
☐ CERCLA Enforcement ☐ Federal Facility ☐ UIC ☐ SPCC ☐ Other: _____
SEND SSSR COPIES TO: ☒ 6SF-AC ☐ 6WQ-SP ☐ ATSDR ☒ State Agency ☐ Other

DISCUSSION:

This property was used for casting and manufacturing of Brake Shoes. Because of past operation, the potential of heavy metal contamination may exist on-site. The sampling activities will focus on the soil exposure and surface water pathways.

Implementing site assessment activities as proposed in the work plan is recommended at this time.

APPROVALS:

Report Reviewed by: Philip Ofosu
(Site Assessment Manager 6SF-RA)

Signature: Philip Ofosu

Date: May/08/08

Disposition Approved by: Jon Rauscher
(Team Leader 6SF-TR)

Signature: Jon Rauscher

Date: 5/08/08

